

HAMPSTEAD GARDEN SUBURB – SIGN AUDIT - WORKS SCHEDULE

Item	Location	Action	Cost	Items Removed	Items Replaced
1	Willifield Green	Concrete bollards (10) – remove	£750 (1)	10	
2	Meadway Court	Concrete bollards – replace with oak posts (2 posts)	£500		2
3	Ossulton Way/Brim Hill	Concrete bollard – replace with oak post	£250		1
4	Harford Walk j/w Vivian Way	Concrete bollards – replace with oak posts (3 posts)	£750		3
5	Meadway Court	Concrete bollards – replace with oak posts (2 posts)			
6	Deansway opp Edmunds Walk	Concrete bollard – remove	£75	1	
7	Brim Hill j/w The Leys	Concrete bollards – replace with oak posts (2 posts)	£500		2
8	Maurice Walk	Concrete bollards – replace with oak posts (2 posts)	£500		2
9	Denison Close	Concrete bollard – replace with oak post	£250		1
10	Brim Hill/ Howard Walk	Concrete bollard – replace with oak post	£250		1
11	Willifield Green at junction	Concrete bollard – remove	£75	1	
12	Sutcliffe Close	Concrete bollard – replace with oak post	£0 (2)		1
13	Greenhalgh Walk / Lyttelton Road	Litter Act sign – remove sign	£65	1	
14	Cornwood Close	Stand-alone cul-de-sac sign – remove sign & post Dilapidated T-sign on lamp-post – replace with new sign	£150	1	1
15	Blandford Close	Stand-alone cul-de-sac sign – remove sign & post	£125	1	
16	Hill Top/ Brookland Hill	Litter Act sign – remove sign & post	£125	1	
17	Howard Walk E/ Brim Hill	Litter Act sign – remove sign & post	£125	1	
18	Howard Walk W/ Brim Hill	Litter Act sign – remove sign & post	£125	1	
19	Norrice Lea/ Nr Lyttelton Rd	Litter Act sign – remove sign & post	£125	1	
20	Kenwood Close	No parking at any time – remove redundant sign and post	£125	1	
21	Wildwood Road, at North End Road.	No parking at any time – remove redundant sign	£0 (2)	1	

HAMPSTEAD GARDEN SUBURB – SIGN AUDIT - WORKS SCHEDULE

Item	Location	Action	Cost	Items Removed	Items Replaced
22	Hampstead Way (N side)	No parking sign on high post – remove sign and post	£0 (2)	1	
23	Winnington Road, O/S No 98	No parking sign on high post – remove sign and post	£125	1	
24	Winnington Road, O/S No 90	No parking sign on high post – remove sign and post	£125	1	
25	Winnington Road	No parking sign on high post – remove sign and post	£125	1	
26	Edmunds Walk	Faded blue “park on one side only” sign at entry to road – remove sign and post. Move cul-de-sac sign to lamp post	£125	1	
27	Edmunds Walk	Rusty old “residents only” sign above the street name sign – remove	£125	1	
28	Edmunds Walk	Humps warning signs – remove signs and post	£650 (3)	1	
29	Edmunds Walk	Two tall posts on the green – remove signs and posts Place one yellow restricted-hours plate on the lamp-post	£150	1	
30	Edmunds Walk outside No.51	Disabled sign - remove tall post and relocate to short post at rear of pavement	£150	1	
31	Deansway (opp Brim Hill)	Humps warning signs – remove post Move signs to adjoining lamp post 15	£150	1	
32	Howard Walk – E and W	Remove the Humps warning signs and posts (2 posts)	£900	2	
33	Grey Close outside No.66 Meadway	Cul de sac sign on high post – remove post Move sign to lamp post	£125	1	
34	Erskine Hill a) on lamp-post 12, b) on stand-alone post O/S No.91	Disabled parking signs with the Barnet logo – replace signs (2 signs)	£80		2
35	Oakwood Road O/S No.51	School Ahead sign – remove post Move sign to adjoining lamp post	£125	1	
36	Kingslay Way/Emmett Close	No Horse Riding sign – remove sign and post	£125	1	
37	Hampstead Way/Mountview Close	Bend Ahead sign – remove post Move sign to adjoining lamp post	£150	1	
38	Corringham Road, O/S No 61 Hampstead Way	Move Residents Parking sign back towards the hedge (Safety issue)	£0		
39	Willifield Green	Beware Old People sign – remove; move Beware Children sign to that location on taller post and remove separate post	£300	1	
40	Linnell Close	Double yellow lines with white hatchings – remove hatchings	£200	1	
41	Oakwood Road	Warning sign when approaching the park – remove post Move sign to lamp post 11	£125	1	
42	Hill Rise	Post stump (feeder pillar) - paint sage green if needs to be retained. Otherwise, remove post	£40		

HAMPSTEAD GARDEN SUBURB – SIGN AUDIT - WORKS SCHEDULE

Item	Location	Action	Cost	Items Removed	Items Replaced
				<u>Total</u>	<u>Total</u>
				Removed	Replaced
				40	16
				Grand total	56
		Total Cost	£8,760		
		HGS RA Contribution - 50%	£4,380		
		LBB Contribution - 50%	£4,380		
		(1) But oak posts might need to be installed later at a cost of £215 per post			
		(2) No charge			
		(3) Maximum. Cost £650 if EDF supply; £275 if private supply			